



February-16, 2023

## Release Notes for ZIP 45G version 95.86.132.7

(appears as 96.86.132.7 on phone)

### *Description of Changes between 95.86.132.6 and 95.86.132.7*

1. IMPORTANT: ZIP 45G phones currently running firmware version 95.84.132.3 or earlier require a '2-Step' upgrade. Phones must first be upgraded to version 95.85.132.1 and then to version 95.86.132.7.

Version 95.85.132.1 is only for the purpose of allowing a phone to be upgraded to a 95.86.132.x version.

The current firmware version of a registered phone may be checked via the 'User Agent' field in the 'View > Device Status' screen of MX Administrator.

2. Firmware version 95.86.132.7 will appear as 96.86.132.7 in the 'Status' screen of the phone. The MX Administrator 'View > Device Status' window will also show a User Agent indicating version 96.86.132.7.

#### *Fixed Issues*

---

##### **Subsystem: ZIP 45G**

ZIPTS-127: ZIP 45G: Enhanced DSS Key (EDK) scripting may not function correctly

#### *Fixed Issues*

---

##### **Subsystem: ZIP 45G**

[ZIPTS-127: ZIP 45G: Enhanced DSS Key \(EDK\) scripting may not function correctly](#)

**Platform:** ZIP 45G

**Description:** Programmable keys configured to utilize Enhanced DSS Key (EDK) scripting may not function correctly. For example, keys configured to accept user input may not recognize keypad input.

**Releases Affected:** From 95.86.132.6